



DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
KAGAWARAN NG KAPALIGIRAN AT LIKAS YAMAN



BAGONG PILIPINAS

MEMORANDUM

TO/FOR : **The Undersecretary**
Field Operations - Luzon, Visayas, and Environment

The Director
Mines and Geosciences Bureau
Environmental Management Bureau

The OIC Director
Policy and Planning Service

FROM : **The Undersecretary**
Policy, Planning and International Affairs

**SUBJECT: DIRECTIVES OF THE SECRETARY DURING EXECOM MEETING
NO. 2024-07 HELD ON 20 FEBRUARY 2024 REGARDING THE
UPDATE ON THE KARST STUDY IN RELATION TO THE
MORATORIUM LIFTING OF ECC IN BORACAY**

DATE : MAR 01 2024

In the discussion of the agenda regarding the Update on the Karst Study in relation to the Moratorium lifting of ECC in Boracay, during Executive Committee Meeting No. 2024-07 held on 20 February 2024, the Secretary instructed the following:

1. Make Engineering Geological and Geohazard Assessment (EGGA) a precondition in the issuance of ECC. The EGGA Report must be reviewed by the MGB and EMB
2. PENRO and CENRO/MENRO to be included in the Levelling Off Meeting with the Aklan LGU to be held in the 1st week of March 2024.
3. Explore possible collaboration with the DPWH regarding the engineering solutions specifically on guidance to building codes and possible public infrastructure. These interventions can be introduced to sustainably manage the ecotourism sites.
4. On the first slide of the presentation on the Integrated Geologic, Geophysical, and Coastal Vulnerability Assessment of Boracay Island, under the Conclusion and Recommendations (Slide No. 29), interchange the positions of bullet one which focuses on the recommendation of minimizing sinkhole risks in Boracay's karst areas through cost-effective drainage control and bullet two which underlines EGGA as a precondition and an additional requirement of the Environmental Impact Assessment (EIA) process prior to the issuance of the Environmental Compliance Certificate (ECC).

5. Explore a possible collaboration with LGU (Governor and Mayor), MPDO, PPDO, MENRO, CENRO on coming up with a comprehensive plan for areas that are sensitive to specific environmental conditions.
6. Summarize and list down issues and possible interventions to be presented to LGUs (Governor and Mayor), MENRO, CENRO, DOT, and other concerned offices/agencies.

Relative thereto, please submit report of compliance to the above-cited directives to the Office of the Chief of Staff via email to osec@denr.gov.ph, copy furnished ouppia@denr.gov.ph, and policy@denr.gov.ph.



ATTY. JONAS R. LEONES

MEMO NO. 2024 - 204




MINES AND GEOSCIENCES BUREAU

Integrated Geologic, Geophysical, and Coastal Vulnerability Assessment of Boracay Island

2018-2022


Karlo L. Queano, Ph.D., Leilanie O. Suerte D.Engg., Ross Dominic D. Agot, Marie Krystel D. Hugo, Madonna Feliz B. Madrigal, Laila Grace B. Indico, Ram Alfred A. Rollan, Aeron Evin C. Dela Cruz, Lawrence Oliver D. Buduhan, Myron Gerard Y. De Guzman, Adrian Nicholl L. Lizada, John Eric N. Ramos, Kristine Joy L. Mojot, Adeline Grace M. Torreda, Ghelsi Grace Mendoza, Abigail G. Dalanao, Shimpai A. Francisco, John Frederick D. Santos




OBJECTIVES

The comprehensive study in Boracay Island aims to:


- 1. Provide baseline information and understanding of the island's geological features;**
- 2. Offer insights into the subsurface layers through geophysical surveys;**
- 3. Identify hazard areas and generate hazard maps based on the baseline information and geophysical surveys; and**
- 4. Evaluate the coastal (physical) vulnerability of the Island.**




*South China Sea
(West Philippine Sea)*




*South China Sea
(West Philippine Sea)*




GEOLOGY OF BORACAY ISLAND AND ITS RELATIONSHIP TO KARST DEVELOPMENT




- Pliocene Sta. Cruz Formation
- Generally of coralline and fossiliferous limestone fragments; bedded
- Numerous solutional cavities
- Uplift of coral reefs related to active tectonics



Active deformation in Central Visayas





Source: Queaño, 2007. *Journal of Geophysical Research*





Source: Queaño, 2007, *Journal of Geophysical Research*





Source: Queafo, 2007, *Journal of Geophysical Research*







Source: Queaño, 2007. *Journal of Geophysical Research*



Active deformation in Central Visayas




Clockwise rotation for Negros, Cebu and Bohol following collision; Boracay falls outside but near to the collision




SINKHOLES AND CAVE OPENINGS IN BORACAY ISLAND



Discussion and cave subsidence sinkholes were identified within Watershed No. 1. Its sporadic ridges form a major drainage system. The largest sinkholes were observed in the watersheds of Watersheds 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100.




The subsidence of the center of Changyuan was observed in a hot spot. It was caused by the subsidence of the center of Changyuan. The center of Changyuan is located in the center of the island.



A



B




D



E


3. A subsidence of the Cave Cave
 E. A cave opening is located in a hot spot. The cave opening is located in the center of the island.
 F. Cave Cave



A cave subsidence sinkhole was identified at the open field of (L) within the Tard Mountain High School. Sinkholes were found at the Tard Mountain High School.




D




A cave subsidence sinkhole is located inside the property of Moneveta. The sinkhole is located in the center of the island. The cave opening is located in the center of the island.

Brgy. Yapak



SINKHOLES AND CAVE OPENINGS IN BORACAY ISLAND




A. A soldier's sandstone was bombed, which is part of Western No. 2. It is situated adjacent to the entrance of the Dark Side of Paradise. Some parts of garbage were removed by B. It is observed that the position of Lapid, Lapid, Lapid is gradually subsiding as manifested by the formation of cracks. C. A vertical displacement of about 1 inch was noted with a horizontal displacement of about 2 inches to the west. D. Erosion pits are already forming towards the sinkhole.




A concrete structure (circular) covered with small stones, wires and grass is exposed to Las Bases Resort. A sapsa bank is situated within the sinkhole. One of the sinkholes is a sapsa bank type with a diameter of about 7 meters. This is where hoodlums are pumped by Las Bases. Two sapsa wells are found where residents utilize the water for bathing.



Brgy. Balabag




MAP OF SUBURBANCE SUSCEPTIBILITY OF BRGY. BALABAG, BORACAY ISLAND




Concrete structure in the field of the sinkhole. The concrete structure is situated within the sinkhole. The concrete structure is situated within the sinkhole.



Classroom and the open field of Brgy. Balabag. Sinkhole is frequently flooded during high tide. The open field has been used for the purpose of providing recreational ground. Concrete structures are situated within the sinkhole. The concrete structure is situated within the sinkhole. The concrete structure is situated within the sinkhole.




SINKHOLES AND CAVE OPENINGS IN BORACAY ISLAND





Crown Regency Resort (Wetland No.5)



A



KARST SUSCEPTIBILITY



Ground walleded cover subsidence sinkhole from LIDAR and threshold data. A 3 floor building with several apartment units is built on the sinkhole. Soil materials are slowly sagging exposing the foundation of the building. Rainwater from the road and the surrounding areas pools the base of the building. Vegetation such as palm indicates that the area is usually water-saturated. It is also observed that the road is slightly tilted towards the building.



Highway along primary Cover subsidence sinkhole located at Boracay 3 zone of Leisure Resorts World property. (Upper right image) Note how the concrete floor is saturated. Pools of water are in a 300 area. (Lower photo) Cracks all over the floor of the house are observed.




Disturbed some houses are now sinking. Some have been exposed during construction of houses. The case is controlled by water erosion (has a height of about 20 feet according to a resident in Sagu Cultural Village)



Brgy. Manoc-Manoc




GEOPHYSICAL SURVEY







Ground Penetrating Radar



1D/2D Electrical Resistivity Survey



OBSERVED ACTIVE SUBSIDENCE IN BORACAY ISLAND



GEOPHYSICAL SURVEY

Barangay Yapak Near Wetland No. 1



YAPAK, BORACAY ISLAND, AKLAN

A


A'

ALTA VISTA ROAD
VES-BCV-02


WETLAND NO. 1
VES-BCV-01



RESISTIVITY PROFILE A-A'
(ER - 1D)






GPR RADARGRAM IN WETLAND 1
LINE BC: ALONG PUKA BEACH ROAD
N1159444 E23154 S118 - N1159451 E23154 S21



(GPR)

GEOPHYSICAL SURVEY

Front of Elizalde's Guesthouse, White Beach, Barangay Balabag




Maximum Depth of Penetration: 25 m
Dielectric Constant: 8




GPR RADARGRAM ALONG THE ROAD IN FRONT OF ELIZALDE PROPERTY
LINE 006 (CD): N11 S8 3.5 E121 S5 12.9 - N11 S8 3.3 E121 S5 13.4

(GPR)



(ER - 2D)




Philippine Sea

Anthropogenic
Activities

BORACAY
ISLAND


Sea Level
Rise

Geology/
Active
Tectonics




Sea level trend

Globally: 3.4 mm/yr (since the 1993-present; satellite)




South East Asia: 2x faster




Intergovernmental Panel on Climate Change (IPCC)
2022 Sea Level Rise Technical Report



Philippines and vicinity: As much as 3x of the global average sea level rise rate
(International Development Research Centre (IDRC), 2015)





Sea level has risen by as much as 5.7-7.0 mm/yr over the Philippine Sea





COASTAL HAZARD ASSESSMENT



Isostatic rebound after 2013 Bohol earthquake




Data Source: NAMRIA




COASTAL HAZARD ASSESSMENT

SHORELINE SHIFT MAP
BORACAY ISLAND, MALAY MUNICIPALITY, Aklan PROVINCE

1:25,000 Scale





Sea
pine Sea)


Anthropogenic
Activities

BORACAY
ISLAND

Sea Level
Rise

Geology/
Active
Tectonics

COASTAL HAZARD ASSESSMENT



GMANews ONLINE
FOR NEWS AUTHORITY

Boracay implements stricter penalties against sand thieves

By AMANDA LAGO, GMA News
Published August 29, 2012 8:20

Gov't work crews demolish illegal structures in Boracay resort

By Richard B. Reyes Jr., Department of Environment and Natural Resources
October 22, 2006 11:20am

AN ORDINANCE AMENDING MUNICIPAL ORDINANCE NO. 141, SERIES OF 2001 (AN ORDINANCE BANNING THE EXTRACTION AND COLLECTION OF WHITE SANDS) PENALIZES IN THE RESORTS OF BORACAY ISLAND.


WHEREAS, Article 2, Section 16 of the Constitution provides that the State shall protect and advance the right of the people to a balanced and healthful ecology in accord with the rhythm and harmony of nature;

Illegal structures demolished along Boracay shoreline

By Deon Pascilla
October 22, 2006 11:20am





Source: "Deparis and del Cantin"



Bathymetry


12° 0' 0" N 11° 58' 48" N 11° 57' 36" N 11° 56' 24" N

121° 52' 48" E 121° 54' 0" E 121° 55' 12" E 121° 56' 24" E 121° 57' 36" E 121° 58' 48" E




CONCLUSION AND RECOMMENDATIONS

- Sinkholes are the primary karst features in Boracay. Therefore, the most cost-effective way to reduce sinkhole risks is by **controlling drainage**. This involves preventing any new water inputs into the soil profile. Such inputs are typically caused by increased runoff from concrete or asphalt surfaces, poorly located soak ways, broken drains and pipelines, unmanaged storm water, or the removal of topsoil.
- Prior to any construction of major infrastructures requiring ECC in all portions of Boracay island, an Engineering Geological and Geohazards Assessment (EGGA) should be required to be undertaken by the proponent by the EMB, per DENR AO2000-28 and MC2000-33. The corresponding report (EGGAR) should be submitted and thoroughly reviewed by the MGB. As a note, the EGGA is an additional requirement of the EIA process **BEFORE** the issuance of the environmental compliance certificate (ECC) or any infrastructure development. It should not be a post-ECC conditionality.




CONCLUSION AND RECOMMENDATIONS

- In the EGGAR report (EGGAR), the project proponent should be able to document in detail the geological hazards (i.e., future climate-change effects such as sea-level rise) based on scientific principles and methods. This should also detail the condition of the subsurface using borehole data. **The EGGAR should be very clear and specific about the measures (both structural and non-structural) that need to be implemented in order to mitigate geohazards and at the same time, avoid any untoward incident that could affect neighbouring areas.** The EGGAR is reviewed by the Mines and Geosciences Bureau (Central and/or Regional). Coastal projects are reviewed by the MGSD-MGB (CO).
- Land developers and managers should make a concerted/coordinated effort **with the LGU to ensure proper management of groundwater resources.** This include avoidance of excessive withdrawal of groundwater that would lead to enhanced ground subsidence and attendant increase in relative sea-level and associated hazards (e.g., saltwater intrusion). Given that Boracay is a highly populated small island with limited groundwater resources and prone to ground subsidence, **tapping of groundwater is not recommended.**



CONCLUSION AND RECOMMENDATIONS

- It is essential to educate all stakeholders and the general population about the intricate relationships among beach processes of erosion and sediment transport; pollution dispersion patterns; the role of natural buffers (coral reefs and coastal vegetation), and anthropogenic activities in marine, coastal and terrestrial areas. To effectively implement and adhere to coastal erosion and proper land development and management guidelines, it is vital to address any misconceptions through a sustained information and education campaign (IEC) to be conducted by the local government, alongside various agencies of the DENR and other relevant agencies.
- The LGU should ensure the protection and enhancement of natural buffers, including coral reefs, seagrasses, and mangroves. The LGU should strictly adhere to and implement existing laws related to the preservation of these critical natural buffers.




CONCLUSION AND RECOMMENDATIONS

- As net coastal erosion affects Boracay, implementing a **setback zone of at least 25 meters plus 5 meters from the highest high tide** is recommended (e.g., for future developments) in the beaches/coastal plain in consideration of potential climate change effects, such as relative sea level rise and ground subsidence. It should be noted that some areas within Boracay show indications of subsidence related to the dissolution features such as sinkholes and caverns.
- **Coastal developments in cliff-bounded areas should be avoided** due to the risk of slope failures (e.g., rock slides or rock falls). Further, constructing at the cliffs edge, especially in the presence of a wave notch at the cliff base, should be discouraged, as these areas are highly susceptible to slope failure. Depending on the type of infrastructures and the result of the geotechnical test of the subsurface, an easement from the cliff edge should be established. At least 20-meter easement from the edge of the cliff is often recommended, subject to change with the result of the engineering/geotechnical results.



CONCLUSION AND RECOMMENDATIONS

- Given Boracay's limited land area and relatively subdued or rolling landscape, which limits sediment sources for coastal replenishment, it is imperative for the Local Government Unit (LGU) and coastal managers to ensure that any construction along the coast does not disrupt natural sediment processes.
- The hauling of beach sands, for building structures; covering exposed tree roots and/or for recreational purposes such as building sandcastles should be strictly prohibited due to the environmental sensitivity of karstic terrains and the limited sediments available for beach nourishment. This activity is prohibited under BP 265.
- The LGUs, with the active participation of communities should make an effort to revegetate coastal areas affected by previous storms or subjected to cutting or burning. The vegetation serves as windbreaks and help stabilize soils and beach sediments.





MINES AND GEOSCIENCES BUREAU

THANK YOU!

*Lands and Marine Geological Survey Division MGB Central Office and Geosciences Division
MGB Regional Office No. VI*

