Republic of the Philippines

Department of Environment and Natural Resources

Visayas Avenue, Diliman, Quezon City, 1100
Trunkline (632) 929-6626; 929-6628; 929-6635; 929-4028; 929-3618
426-0465; 426-0001; 426-0347; 426-0480; 426-0491
Voice-Over-Internet-Protocol (VOIP) Trunkline (632) 988-3367
Website: http://www.denr.gov.ph / E-mail: web@denrgov.ph

MEMORANDUM:

FOR/TO : ALL CONCERNED OFFICIALS AND EMPLOYEES

DENR Central Office

HACKETT SECURITY SERVICES

Detachment Commander

D' TRIUMPH CLEANERS ALLIED SERVICES, INC.

Supervisor

FROM: THE DIRECTOR

Administrative Service

SUBJECT : CLEANLINESS OF FIRE EXITS AND OTHER AREAS

AT THE DENR-CO MAIN BUILDING

DATE : 05 AUGUST 2022

This is relative to the conducted inspection of the Building Management Section to the DENR Central Office Main Building last 04 August 2022.

Upon observation during inspection, the fire exits contain unnecessary objects and materials which may cause obstructions in case of emergency such as various plants, old files, containers, and food wastes among others.

Other areas particularly hallways and passageways must be free from any obstructions. Moreover, the air-conditioning unit (ACU) condenser area located at third floor must be free from any hazardous materials such as flammable fluids, old files, and scrap papers.


To ensure the safety of DENR Officials and Employees and in compliance with the Environmental Management System, this Office reiterates to maintain cleanliness and observe appropriate use of spaces. It is recommended to proceed in the clearing of the abovementioned areas.

For information and cooperation.

ROLANDO R. CASTRO

ROOFTOP







SIXTH FLOOR







FIFTH FLOOR








FOURTH FLOOR







THIRD FLOOR







SECOND FLOOR







GROUND FLOOR







BASEMENT







GROUNDS AREA

