

### Republic of the Philippines

### **Department of Environment and Natural Resources**

Visayas Avenue, Diliman, Quezon City, 1100
Trunkline (632) 929-6626; 929-6628; 929-6635; 929-4028; 929-3618
426-0465; 426-0001; 426-0347; 426-0480; 426-0491
Voice-Over-Internet-Protocol (VOIP) Trunkline (632) 988-3367
Website: <a href="http://www.denr.gov.ph/">http://www.denr.gov.ph/</a> E-mail: <a href="mailto:web@denrgov.ph/">web@denrgov.ph/</a>

#### **MEMORANDUM:**

FOR/TO

: ALL CONCERNED OFFICIALS AND EMPLOYEES

DENR Central Office

HACKETT SECURITY SERVICES

**Detachment Commander** 

D' TRIUMPH CLEANERS ALLIED SERVICES, INC.

Supervisor

**FROM** 

: THE DIRECTOR

Administrative Service

**SUBJECT** 

: CLEANLINESS OF FIRE EXITS AND OTHER AREAS

AT THE DENR-CO MAIN BUILDING

DATE

: 25 NOVEMBER 2022

This is relative to the conducted inspection of the Building Management Section to the DENR Central Office Main Building last 24 November 2022.

Upon observation during inspection, the fire exits contain unnecessary objects and materials which may cause obstructions in case of emergency such as old files, IT related accessories, containers, and food wastes among others.

Furthermore, other areas particularly hallways and passageways must be free from any obstructions.

To ensure the safety of DENR Officials and Employees and in compliance with the Environmental Management System, this Office reiterates to maintain cleanliness and observe appropriate use of spaces. It is recommended to proceed in the clearing of the abovementioned areas.

For information and cooperation.

ROLANDO R. CASTRO

### 2<sup>ND</sup> FLOOR FIRE EXIT










## 3<sup>RD</sup> FLOOR GENSAN EXIT








# SEC'S EXIT (4<sup>TH</sup> FLOOR)





4<sup>TH</sup> FLOOR SEC STAFF GOING TO 3<sup>RD</sup> FLOOR
















**5<sup>TH</sup> FLOOR USEC FRAGADA** 











# **5**<sup>TH</sup> FLOOR ASEC CAGUIOA





6<sup>TH</sup> FLOOR SCIS







